

Avon Grove School District

Meeting Agenda May 18, 2017 7:00pm - 8:30pm
<p>Meeting Purpose: The purpose of this meeting is to validate the priorities that were generated from individual scoring of building categories and features developed during the April meeting. FIG members will work together to discuss and determine if the priorities accurately reflect the consensus of the group.</p> <p>The information collected over time from the small and whole group debriefs will be crafted to present a Committee recommendation to the AGSD Board.</p> <p>Guiding Questions:</p> <ol style="list-style-type: none"> 1. Does the building score for each school accurately represent the priority, in order of importance, for the Avon Grove School District? <ol style="list-style-type: none"> a. Discuss as a group and list talking points. 2. For each specific school, which features have emerged with the highest level of need? <ol style="list-style-type: none"> a. Does that the accurately reflect the priority in order of importance?
<p>Attendees:</p> <p>Facilitator(s): Kalia Reynolds, Mike Snopkowski</p>
<p>Meeting Objectives:</p> <ol style="list-style-type: none"> 1. Revisit Committee Norms 2. Review the Components of the Decision Matrix 3. Confirm priorities by buildings, categories, and features
<p>Considerations / Follow-Up:</p> <ul style="list-style-type: none"> ● Developed Norms
<p>Schedule:</p>

Time	Minutes	Activity
7:00	10	Welcome Review Purpose of the Meeting Revisit Norms
7:10	40	Group Assignment: Decision Matrix - Focus on Guiding Questions
7:50	30	Carousel Activity: Debrief Priorities by Building, Category and Feature
8:20	5	Confirm Priorities
8:25	5	Confirm Next Meeting Date Dismiss

FIG MEETING 5/18/2017 - GROUP EXERCISE SUMMARY

		AGHS	FSE	PLE	AGIS
GROUP	PRIORITY RANKING	1	2	3	4
MORLEY, WALKER, YOUNG		Classrooms	Classroom space - modulars	Modulars will be issue	Maker "space"
		Common Spaces	Common Space	Common space	Bathroom - doors
		External Features - Outdoor & Athletics	External Features - Outdoor & Athletics		
		Mechanical - Electrical & Tech			
		Related Service			
OTHER GROUP FEEDBACK:		What about pure capacity? School for 1440 with 1880 students?		What about plumbing issues?	
		Want to understand comment about external features?	Want to understand comment about external features?		
		Agree with priority ranking, classrooms, common space and mechanical			

GROUP	PRIORITY RANKING	AGHS	PLE	FSE	AGIS	BOB	JOHN	UWE	JEFF
	SUB-RANKING	1	2	3	4				
AUERBACH, WEIDENMULLER, BEUSCHER, BILLIG		Current conditions don't support learning	Buildings too small for K-2	Building doesn't hold 3 grades 6, 7, 8	4th priority out of all schools	FSE	AGHS	AGHS	AGHS
	Tier 1	OK Classroom Common space Mechanical	Classroom Mechanical	Classroom	OK Classroom Common (space) Mechanical External Related Services *Cafeteria	AGHS	PLE	PLE	FSE
	Tier 2	OK Related services External Features	Common (space) External Related Services	Common (space) Related Services Mechanical		PLE	FSE	FSE	PLE
	Tier 3			External		AGIS	AGIS	AGIS	AGIS
		Why related services so high?		3 grades are preferred		What is wrong with the café?			
OTHER GROUP FEEDBACK:				External: - Landlocked Insufficient field space -Middle School field					

		AGHS	FSE	PLE	AGIS
GROUP	PRIORITY RANKING	1	2	3	4
RUDDY, FARINA, HAMMERSCHMIDT		Class sizes are acceptable (# of students)	Capacity Issues - Modulars - Insufficient for 6-8 MS	Disagree with group ranking: 3 not 4 Has: - Plumbing issues - Modulars - Entrance Safety Issues	Disagree with gymnasium ranking - ranked too high
		Room sizes are too small for functional use	No Auditorium - Curricular - Community		
		Capacity PDE = 1440 AGHS = 1860 +420			
		Common areas too small - Café, auditorium, storage, hallway			
		Poor community use			
OTHER GROUP FEEDBACK:		Why is class size listed?	Footprint too small for outdoor spaces: - 1 athletic field - Gym classes in parking lot - Kids bussed to other fields		
		Room issues are more complex than size			

AGHS			
GROUP	MORLEY, WALKER, YOUNG	AUERBACH, WEIDENMULLER, BEUSCHER, BILLIG	RUDDY, FARINA, HAMMERSCHMIDT
PRIORITY RANKING	1	1	1
	Classrooms	Sub-ranking 3.3	Class sizes are acceptable (# of students)
	Common Spaces	Current conditions don't support learning	Room sizes are too small for functional use
	External Features - Outdoor & Athletics	OK Classroom Common space Mechanical	Capacity PDE = 1440 AGHS = 1860 +420
	Mechanical - Electrical & Tech	OK Related services External Features	Common areas too small - Café, auditorium, storage, hallway
	Related Service		Poor community use
OTHER GROUP FEEDBACK:	What about pure capacity? School for 1440 with 1880 students?	Why related services so high?	Why is class size listed?
	Want to understand comment about external features?		Room issues are more complex than size
	Agree with priority ranking, classrooms, common space and mechanical		

FSE			
GROUP	MORLEY, WALKER, YOUNG	AUERBACH, WEIDENMULLER, BEUSCHER, BILLIG	RUDDY, FARINA, HAMMERSCHMIDT
PRIORITY RANKING	2	3	2
	Classroom space - modulars	Sub-ranking 3.1	Capacity Issues - Modulars - Insufficient for 6-8 MS
	Common Space	Building doesn't hold 3 grades 6, 7, 8	No Auditorium - Curricular - Community
	External Features - Outdoor & Athletics	Classroom	
		Common (space) Related Services Mechanical	
		External	
OTHER GROUP FEEDBACK:		3 grades are preferred	Footprint too small for outdoor spaces: - 1 athletic field - Gym classes in parking lot - Kids bussed to other fields
	Want to understand comment about external features?	External: - Landlocked - Insufficient field space - Middle School field	

AGIS			
GROUP	MORLEY, WALKER, YOUNG	AUERBACH, WEIDENMULLER, BEUSCHER, BILLIG	RUDDY, FARINA, HAMMERSCHMIDT
PRIORITY RANKING	4	4	4
	Maker "space"	Sub-ranking 2.6	Disagree with gymnasium ranking - ranked too high
	Bathroom - doors	4th priority out of all schools	
		OK Classroom Common (space) Mechanical External Related Services *Cafeteria	
OTHER GROUP FEEDBACK:		What is wrong with the café?	

PLE

GROUP	MORLEY, WALKER, YOUNG	AUERBACH, WEIDENMULLER, BEUSCHER, BILLIG	RUDDY, FARINA, HAMMERSCHMIDT
PRIORITY RANKING	3	2	3
	Modulars will be issue	Sub-ranking 2.2	Disagree with group ranking: 3 not 4 Has: - Plumbing issues - Modulars - Entrance Safety Issues
	Common space	Buildings too small for K-2	
		Classroom Mechanical	
		Common (space) External Related Services	
OTHER GROUP FEEDBACK:	What about plumbing issues?		